10 CFR 2.201 SAFETY INSPECTION				
Cogentrix of Virginia, Inc. PO Box 112 912 E. Randolph Rd. Hopewell, VA 23860		U.S. Nuclear Regulatory Commission 101 Marietta St. NW Suite 2900 Atlanta, GA 30323		
3. DOCKET NUMBER(S)	4. LICENSE NUMBERIS		5. DATE OF INSPECTION	
030-31233	45-25062-01		12/19/89	
Licersee				
Regulatory Commissions (NRC) rules at	nd regulations and the conditions of yo	our license. The inspection	tion safety and to compliance with the Nucl n consisted of selective examinations of proc as a result of this inspection are as follows:	
1. Within the scope of this inspection	on, no violations were observed.			
2. The inspector also verified the st	eps you have taken to correct the viola	tions identified during the	e last inspection. We have no further question	ons on
those actions at this time.				
	your activities, as checked below, were TION which is required to be posted in			
[]A			was not properly posted to indicate the particle of the control of	presence
of a			. 10 CFR 20.203(b), (c), (d), (e) o	or 34.42.
B. Containers located in	ice of radioactive material. 10 CFR 20	203(f)(1), or (f)(2).	were not p	properly
Пс			of sealed sources were not performed at the	e proper
frequencies 10 CFR		License C	ondition Number	
D Records of			were not properly mai	intained.
10 CFR		or License Condition Nu	mber	
E. Documents were not properly	y posted or otherwise made available.	10 CFR 19.11.		
F Reports or politications of			were not made in acc	cordance
C)*				
U'				
			the violations identified in the items checked further response will be submitted unless rec	
9003020256 891 RE02 LIC30	219	182	Byce:	lala
45-25062-01 SIGNATURE - LICEN	PDC W DATE	SIGNATUR	RE - NAC INSPECTOR	DATE

IEO7 OL