

APPENDIX ANOTICE OF VIOLATION

Alabama Power Company  
Farley Unit 1

License No. NPF-2

Based on the NRC inspection August 12-14, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Technical Specifications 6.8.1 and 6.8.2, written procedures shall be established, implemented and maintained covering the applicable procedures recommended in Appendix "A" of Regulatory Guide 1.33, November, 1972 and each procedure and administrative procedure including temporary changes shall be reviewed prior to implementation as set forth in Technical Specification 6.5. Appendix A of Regulatory Guide 1.33 states in part that chemical and radiochemical procedures should be written to prescribe the nature and frequency of sampling and analyses and that these procedures should specify laboratory instructions and calibration of laboratory equipment.

Contrary to the above, during the period of August 1978 to August, 1980, unreviewed changes were made in the calibration step of Procedure FNP-0-CP-04, Potentiometric Determination of Fluoride Ion in Aqueous Solutions.

This is a deficiency.