

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II

101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

SEP 1 1 1980

In Reply Refer To: RII:VLB 50-348/80-23 50-364/80-30

> Alabama Power Company ATTN: R. P. McDonald

Vice President-Nuclear Generation

P. O. Box 2641

Birmingham, AL 35291

Gentlemen:

This refers to the inspection conducted by V. L. Brownlee of this office on August 14-15, 1980, of activities authorized by NRC License No. NPF-2 and Construction Permit No. CPPR-36 for the Farley facility, and to the discussion of our findings held with J. D. Woodard at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were disclosed.

We have examined actions you have taken with regard to previously identified enforcement matters. These are discussed in the enclosed inspection report.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

C. E. Murphy, Chief

Reactor Construction and Engineering

Support Branch

Enclosure: (See Page 2)

8010240661



Enclosure:

Inspection Report Nos. 50-348/80-23 and 50-364/80-30

cc w/encl:

- A. R. Barton, Executive Vice President
- F. L. Clayton, Jr., Senior Vice President
- H. O. Thrash, Manager-Nuclear Generation
- O. D. Kingsley, Jr., Manager, Nuclear Engineering and Technical Services
- J. W. McGowan, Manager-Operations Quality Assurance
- W. G. Hairston, III, Plant Manager
- W. C. Petty, Manager-Quality Assurance (Design and Construction)