Cerctial Fles

Docket No. 70-36

Combustion Engineering, Inc. ATTN: Mr. H. V. Lichtenberger Vice President - Manufacturing Nuclear Power Systems Windsor, CT 06095





It has been our po cy to keep you informed of matters which are important to continued cooperation which otherwise may be of particular interest to you. We believe this exchant f information has proved beneficial to both you and the Commission. This is in keeping with that policy.

A major consideration growing 'of the Three Mile Island Incident, was the need for realignment of the 'Office of Inspection and Enforcement (IE) organizational structure. Recommend 'ions were included in NUREG-0660, "NRC Action Plan Developed as a Result 'the TMI-2 Accident." The new structure, addressed in the TMI-2 action 'a, is simed at better management of the preventive inspection program, quicks and more efficient response to emergencies, and closer working relationships with the States and licensee management.

Reorganization of the NRC Regional Offices will become effective February 16, 1981. The enclosures show the new organizational structure for Region III. These charts identify supervisory and other key personnel who will be cognizant of licensed activities, State programs and other functions. There will be no resident inspector reassignments; however, in some areas supervision responsible for certain resident inspector offices has been changed.

The 24-hour NRC Region III telephone number (312-932-2500) and the Emergency Notification System remain unchanged. New telephone extensions for the staff will be provided as they become available.

You will observe from the enclosed charts that the essential elements of the new organization are (1) project management including the resident inspector offices, (2) engineering and other technical support functions including the reactor, fuel facilities and materials programs, and (3) emergency preparedness. Included on the charts are the management structure, investigative and enforcement staff, State liaison, public affairs and resident inspector program functions.

We look forward to your continued cooperation with this office, and, should you have questions regarding the subject of this letter please call me.

Sincerely,


James G. Keppler Director

Faclosures:

- Overall Region III
 Organization Chart
- Division of Resident and Reactor Project Inspection Chart
- Division of Engineering and Technical Inspection Chart
- 4. Division of Emergency
 Preparedness & Operational
 Support Chart

cc w/encls: J. A. Rode, Plant Manager Central Files

RIM Davis/np 2/13/81 RIII CYK Keppler



DWMP 846304626 &

PROJECT INSPECTION

R. F. Heishman, Acting Director

Projects Branch 1 R. C. Knop, Acting Chief Reactor Projects Sec. 1A D. Boyd, Chief Big Rock Point Midland Palisades Research Reactor, Fuel Facilities Reactor Projects Sec. 1B D. Hayes, Chief D. C. Cook Braidwood Byron Zion Reactor Projects Sec. 10 F. Reimann, Acting Chief Clinton Dresden La Salle

Quad-Cities

Projects Branch 2

G. Fiorelli, Chief

Reactor Projects Sec. 2A

J. Konklin, Acting Chief

Callaway Fermi Bailly Kewaunee Point Beach

Reactor Projects Sec. 2B


R. Warnick, Chief

Davis-Besse La Crosse Perry Zimmer

Reactor Projects Sec. 2C

W. Little, Chief

Duane Arnold Marble Hill Monticello Prairie Island



of and Emergency Preparedness Licensing Branch J. Pagliaro 8765640289 Emergency Preparedness & Program Support Branch C. J. Paperiello, Chi f Environmental Inspection W. Axelson, Acting Chief Emergency Preparedness Incident Response Emergency Plans/Drills T. Tambling, Acting Chief DIVISION OF EMERGENCY PREPAREDNESS AND OPERATIONAL SUPPORT J. A. Hind, Acting Director State Liaison Officer W. B. Menczer Administrative Support Br. Performance Appraisal H. Pappas, Chief Branch

Independent Measurements and Environmental Protection Sec.

M. Schumacher, Acting Chief

Labs and Verification Program

Emergency Preparedness Section

Operational Support Section

Management Informations Systems, SALP, Event Review, Bulletins, Circulars, Notices