

YANKEE ATOMIC ELECTRIC COMPANY

Telephone 617 872-8100



1671 Worcester Road, Framingham, Massachusetts 01701

2.C.2.1

FYR 81-30

February 27, 1981

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406



Attention: Mr. Boyce H. Grier, Director

References: License No. DPR-3 (Docket No. 50-29)

Subject: Yankee Rowe 1980 Annual Report

Dear Sir:

Enclosed herewith please find three (3) copies of the Yankee Rowe Annual Report, which describes the facility changes, tests and experiments conducted without prior NRC approval during the year 1980. This report is submitted in accordance with 10CFR50.59(b) and Yankee Rowe Technical Specification 6.9.2b requirements.

Also included in this report (and in future annual reports) is a summary of safety valve and relief valve failures and challenges as required by TMI Action Plan Item II.K.3.3.

We trust this information is acceptable to you; however, should you have any questions, please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

D. E. Moody
Manager of Operations

cc: Director of Inspection and Enforcement
United States Nuclear Regulatory Commission
Washington, D. C. 20555

A008
S
1/c

8103090 SII