



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 2, 1981

2CAN078103



Director of Nuclear Reactor Regulation
ATTN: Robert A. Clark, Chief
Operating Reactors Branch #3
Division of Licensing
U. S. Nuclear Regulatory Comm.
Washington, D.C. 20555

SUBJECT: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Low Temperature Overpressurization
(File: 2-1510)

Gentlemen:

Our letter to you of March 30, 1981, responded to staff questions regarding the ANO-2 Low Temperature Overpressurization (LTOP) modifications. Our response for question one (1) contained an error which should be corrected. It should more properly have stated "hydro test once per refueling in accordance with ASME Section XI."

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:lp

*Aool
S. 11*

8107130190 810702
PDR ADOCK 05000368
P PDR