



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

JUL 9 1981

Docket No. 50-454  
Docket No. 50-455

Commonwealth Edison Company  
ATTN: Mr. Cordell Reed  
Vice President  
Post Office Box 767  
Chicago, IL 60690

Gentlemen:

Thank you for your letter dated June 25, 1981, responding to our questions regarding Byron cable tray stiffener weld quality which we brought to your attention in our letter dated April 23, 1981. On the basis of our review of the information provided in your letters dated February 26, 1981 and June 25, 1981, we have no further questions on this matter at this time. However, please notify this office when you have amended the FSAR regarding cable tray weld inspection criteria.

Your cooperation with us is appreciated.

Sincerely,

*C. E. Norelius*

C. E. Norelius, Acting Director  
Division of Engineering and  
Technical Inspection

cc: J. S. Abel, Director  
of Nuclear Licensing  
Gunner Sorensen, Site  
Project Superintendent  
V. I. Schlosser,  
Project Manager  
R. E. Querio, Station  
Superintendent

cc w/ltr dtd 6/25/81:  
DMB/Document Control Desk (RIDS)  
Mary Jo Murray, Office of  
Assistant Attorney General  
Myron M. Cherry



*IEO1  
5/1/1*

8107140731 810709  
PDR ADOCK 05000454  
PDR  
Q