

FOR DCS PROCESSING
Original document not available
to NRC.
Certified by *Dorothy Noack*

WAYNE W. WONG, M. D.
615 PIKOI, SUITE 510
HONOLULU, HAWAII 96814
—
TELEPHONE 808 523-9393

June 29, 1981

Mr. H. E. Book, Chief
Radiological Safety Branch
1990 N. California Boulevard
Suite 202, Walnut Creek Plaza
Walnut Creek, California 94596

Re: License No.
53-11701-01
Subject: NRC Inspec-
tion

Dear Mr. Book:

Per my conversation with Mr. Grayson this morning,
June 29, 1981, regarding NRC Inspection that from now
on we will take the corrective steps for full compliance
for the leak tests.

Leak tests were performed by the Radiation Control
Center at the State Board of Health from 1974-1977, and
the tests were negative throughout those years.

Thank you.

Sincerely,

Wayne W. Wong, M.D.

Wayne W. Wong, M.D.