

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION V

1990 N. CALIFORNIA BOULEVARD SUITE 202, WALNUT CREEK PLAZA WALNUT CREEK, CALIFORNIA 94596

July 2, 1981

License No. 36-15080-01

Department of the Interior Bureau of Indian Affairs Warm Springs Agency Warm Springs, Oregon 97761

Attention: Mr. Ray Welch

Acting Superintendent

Gentlemen:

Subject: NRC Inspection

This refers to the routine safety inspection conducted by Mr. J. F. Pang of this office on May 20, 1981 of activities authorized by NRC License No. 36-15080-01 and to the discussion of our findings held by Mr. Pang with you and other members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel and observations by the inspector.

During this inspection, it was found that certain of your activities appeared to be in noncompliance with NRC requirements. The items and references to the pertinent requirements are listed in Appendix A. These items have been categorized into severity levels as described in the Federal Register Notice (45 FR 66754) dated October 7, 1980.

Your response to this notice is to be submitted in accordance with the provisions of 10 CFR 2.201 as stated in Appendix A, Notice of Violation.

Pursuant to the action taken by the licensee relative to the violation stated in paragraph C, Appendix A, no further response to this item is required.

I EOT

If you have any questions on this matter or concerning this inspection, please telephone Mr. Pang on 415-943-3700.

Sincerely,

A. E. Book

H. E. Book, Chief Radiological Safety Branch

Enclosure:

A. Notice of Violation