Return TD: WMUR 46155 Docket 40-7869

DISTRIBUTION

PDR WMUR r/f WMUR c/f NMSS r/f

WM r/f

Mill File IE & HQ (2) KBWestbrook

JJL inehan

RAScarano REBrowning

JBMartin

BPFisher

HJPettengil1

DEMartin

JUL 0 9 1981

WMUR: KBW

Docket No. 40-7869

MEMORANDUM FOR: LeRoy S. Person

Operating Facilities Section I Uranium Recovery Licensing Branch Division of Waste Management

THRU:

John J. Linehan, Section Leader Operating Facilities Section I Uranium Recovery Licensing Branch Division of Waste Management

FROM:

Kristin B. Westbrook

Operating Facilities Section I Uranium Recovery Licensing Branch Division of Waste Management

SUBJECT:

SURFACE AND GROUNDWATER HYDROLOGY REVIEW OF SEMIANNUAL

EFFLUENT (1980-2) REPORT FOR PLATEAU RESOURCES LIMITED(PRL)

HEAP LEACH

This facility is being decommissioned. The site has no water impoundments and no running surface water except for intermittent rain runoff. It was reported that there were no liquid effluent releases. No water monitoring data was presented in the report.

No monitoring of surface water is required under this license. However, there are two water wells that have, according to PRL, been monitored quarterly. The well monitoring is required by license SUA-1013, Condition 10. As part of our review of the decommissioning of this facility, a meeting was held with PRL on June 25, 1981. At this meeting PRL was requested and committed to submitting all groundwater monitoring data collected to date. Based on the above, no further action is necessary at this time.

Original Signed By:

Kristin B. Westbrook Operating Facilities Section I Uranium Recovery Licensing Branch Division of Waste Management

Case closec 04007869m028

107220337 810709
PDR ADOCK 04007869
C PDR

OFFICE WMUR

WMUR

WMUR

SURNAME KBWastbrook Jucinpun

DATE FORM 318 (10/80) NRCM 0244

OFFICIAL RECORD COPY

1 USGPO 1980—329-824