

APPENDIX A

NOTICE OF VIOLATION

Rockingham Memorial Hospital

License No. 45-05594-01

As a result of the inspection conducted on June 4, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 56754 (October 7, 1980), the following violation was identified.

License Condition 16 requires that licensed material be used in accordance with statements and procedures contained in your application dated August 1, 1977 and your letter dated November 7, 1977. One procedure in your letter of November 7, 1977, requires that areas be monitored for contamination weekly.

Contrary to the above, the requirement to monitor areas for contamination weekly was not met in that the required tests have not been performed since April 1978.

This is a Severity Level V Violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Date: JUN 26 1981

8107240269 810715
NMS LIC30
45-05594-01 PDR