



VIRGINIA POULTRY INDUSTRY LABORATORY, INC.

Box 1036, Harrisonbur , Virginia 22801 • 434-5577

July 9, 1981

Mr. A. F. Gibson, Chief Technical Inspection Branch Engineering Technical Inspection Division United States Nuclear Regulatory Commission, Region II 101 Marietta St., N.W., Suite 3100 Atlanta, GA 30305

RE: Report No. 45-16566-01/81-01

Dear Mr. Gibson

We regret that our laboratory was in violation on the two items listed in your notice. Both were due to oversights for the following reasons:

- A. We thought that the licensing applied to any Harrisonburg address and not to the specific street location. Upon notification by Mr. Brown of your office, we amplied for an amended license and are awaiting receipt of it.
- B. Apparently, copies of 10CFR 19 and 10CFR 20, along with the regulations listing the required posting, had been lost or discarded by my predecessor, Charles Smithers. I was not aware of the requirement until the visit by Mr. Brown. Having obtained copies of 10CFR 19 and 10CFR 20, we posted them on June 8, 1981. The license will be posted in the same frame as these documents immediately upon its receipt from your office.

Mr. Gibson, we believe that, upon receipt of our new license, based on Mr. Brown's inspection and the corrective actions taken as outlined above, we will be in full compliance with all regulations of the Nuclear Regulatory Commission.

Sincerely,

Barry W. Miller

Director

BWM: njh

8107240281 810716 NMS LIC30 45-16566-01 PDR