



Commonwealth Edison
 Zion Generating Station
 Shiloh Blvd. & Lake Michigan
 Zion, Illinois 60099
 Telephone 312/746-2084

DMB/LER

July 17, 1981

Mr. James C. Keppler
 Regional Director
 Office of Inspection and Enforcement
 Region III
 U.S. Nuclear Regulatory Commission
 Glen Ellyn, Illinois 60137



Reference: Zion Generating Station
 Docket No. 50-295/DPR-39
 Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Updated Reportable Occurrence Report No. 50-295/81-04 for Zion Generating Station. The original was submitted March 6, 1981.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.B.2, which states that conditions leading to operation in a degraded mode permitted by a limiting condition for operation require a 30 day written report.

Very truly yours,

K. L. Graesser

K. L. Graesser
 Superintendent
 Zion Station

cc: J. Kohler/J. Waters

Enclosure: Updated Reportable Occurrence Report No. 50-295/81-04

IE22
3
1/1

8107240323 810717
 PDR ADOCK 05000295
 S PDR

JUL 21 1981