License: 11-15946-01

Morrison-Knudsen Company
ATTN: R. Ben Rietze, Director of Safety and
Environmental Services
P. O. Box 7808
Boise, Idaho 83729



Gentlemen:

This refers to the safety inspection conducted by Mr. D. B. Spitzberg of this office on June 17, 1981, of the activities authorized by NRC Byproduct Material License 11-15946-01 and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements and observations by the inspector.

No violations of NRC requirements were found during the inspection.

Mr. Spitzberg also reviewed the action you had taken with respect to one violation observed during our previous inspection, which was conducted March 26-27, 1979. He verified that the corrective action with respect to this item was implemented as stated in your reply of April 16, 1979, to our letter dated April 10, 1979.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

"Original Signed by: G. D. BROWN"

Glen D. Brown, Chief Technical Inspection Branch I 507

8107280385 810707 NMS LIC30 11-15946-01 PDR

OFFICE	TIB-RIV DBS	MRPS Se	IES	DD	TIE	
			78.8		GDB rown	
	6/29/81	6/3/81	16/2/81		6/ /81	