License No. SUB-1244

Department of the Air Force USAF Tactical Fighter Weapons Center Nellis Air Force Base, Nevad 89191

Attention: Col. John C. Willis,

Hospital Commander

Gentlemen:

Subject: NRC INSPECTION

This refers to the routine safety inspection conducted by Mr. J. F. Pang of this office on June 23, 1981 of activities authorized by NRC License No. SUB-1244 and to the discussion of our findings held by Mr. Pang with you and other members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel and observations by the inspector.

During this inspection, it was found that certain of your activities appeared to be in noncompliance with NRC requirements. The items and references to the pertinent requirements are listed in Appendix A. These items have been categorized into severity levels as described in the Federal Register Notice (45 FR 66754) dated October 7, 1980.

Your response to this notice is to be submitted in accordance with the provisions of 10 CFR 2.201 as stated in Appendix A, Notice of Violation.

If you have any questions on this matter or concerning this inspection, please telephone Mr. Pang on 415-943-3700.

Sincerely,

Sent to Reproduction, HQ, for distribution

Original signed by H. E. Book

Distributed by RV:

H. E. Book, Chief Radiological Safety Branch IEO7

8108050329 810720 PDR ADOCK 04008431

OFFICE RV Notice of Fixton RV SURNAME PANG: frj TP THOMAS BOOK TO DATE 7/11/81 7/11/81