OFFICIAL COL TENNESSEE VALLEY AUTHORITY CHATTANOOGA, TENNESSEE 37401 500A Chestnut Street Tower II 11 ... 58 05:01 March 24, 1981 81-040-032 Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303 Dear Mr. O'Reilly: TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 -DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - 10 CFR 21 REPORT This is to supplement the subject report transmitted to you dated March 20, 1981. All unit 1 ERCW and CCS valve operator switch compartment heaters were disconnected by March 12, except for five on the ERCW system. These five switch housings did not indicate any damage, and their compartment heaters were disconnected by March 19. This was reported by Walter E. Andrews to the Sequoyah IE resident inspector,

Ed Ford, on March 24, 1981.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

James R. Durill

A. G. Parris Manager of Power

B108070146 B1032