FORM NRC-591 (3-77)	U.S. NUCLEAR REGULATORY COMMISSION
	INSPSCTION FINDINGS AND LICENSEE ACKNOWLEDGMENT
1 LICENSEE	2. REGIONAL OFFICE
- EI D + L.	
E. T. du Pont de Dhote Produils	Nemours U.S. N.R.C.
Chest and Run	Lab 62 Pank Asance
Chestmit nun	IF 19898 Kingor Pausin PA 19406
S. DOCKET NUMBER(S)	4. LICENSE NUMBER(S) B. DATE OF INSPECTION
30-386	2 07-00455-30 July 31,1981
6. INSPECTION FINDINGS The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and repre- sentative records, interviews with personnel, and observations by the inspector. The findings as a result of this upparties are as follows.	
	A Principal
	ince or unsafe conditions were found.
	mpliance related to records, signs, and labels were .ound: EAUG 07 1981 Fol
	not properly posted to indicate the presence of a RADIATION AREA 10 CER 20.203(b) 0634.42
B. Rooms or areas were 10 CFR 20.203(c) (not properly posted to indicate the presence of a HIGH P 'DIVISION AREA.
C. Rooms or areas were 10 CFR 20.203(d)	not properly posted to indicate the presence of an AIRBORNE RADIO ACTIVITY AREA.
D. Rooms or areas were	not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)
E. Containers were not 10 CFR 20.203(f) (properly labeled to indicate the presence of RADIOACTIVE MATERIAL.) or (f) (2)
F. A current copy of 1 made available. 10 C	CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or FR 20.206(b)
G. Form NRC-3 was no	t properly posted. 10 CFR 20.206(c)
H. Records of the radia	tion exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)
I. Records of surveys of	r disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)
J. Reco. 's of receipt, 10 CFR 30.51, 40.6	ransfer, disposal, export or inventory of licensed material were not properly maintained. I or 70.51
K. Records of leak test	were not maintained as prescribed in your license, or 10 CFR 34.25(c)
L. Records of inventor	es were not maintained. 10 CFR 34.26
M. Utilization logs were	not maintained. 10 CFR 34.27
N. Records of radiation	survey instrument calibration were not maintained. 10 CFR 34.24
O. Records of telethera	py electrical interlock tests were not maintained as prescribed in your license.
P. Other	
	Jenny m Jahannen
	xplained and I understand the items of noncompliance liste ' above. The items of
8108100357 9107	rrected within the next 30 days.
NMS LIC30	PDR
(Date)	(Licensee Representative – Title or Position)
the second	

ORIGINAL TO LICENSEE