

Appendix A

NOTICE OF VIOLATION

Wooddell Logging, Inc.

License No. 12-19038-01

As a result of the inspection conducted on July 21 and 22, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

License Condition No. 18 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in application dated May 10, 1979 and letter dated November 16, 1979. Included in the application (Item No. 11 a) is a requirement to calibrate survey meters every six months.


Contrary to the above requirement, on the day of the inspection records showed that two survey meters had not been calibrated within the six month interval. Instrument No. 3895 was calibrated November 28, 1980; instrument No. 6530 was calibrated July 22, 1980. Both instruments were used until July 3, 1981, a period greater than six months.

This is a Severity Level V violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation. Consideration may be given to extending your response time for good cause shown.

8-5-81

Dated



D. G. Wiedeman, Acting Chief
Materials Radiation Protection
Section 1