

SEP 17 1981



Docket No.: 50-382

MEMORANDUM FOR: P. S. Check, Assistant Director for Plant Systems, DSI  
 B. K. Grimes, Director, Division of Emergency Preparedness, IE  
 W. V. Johnston, Assistant Director for Materials & Qualifications Engineering, DE  
 L. S. Rubenstein, Assistant Director for Core and Containment Systems, DSI  
 J. D. Saltzman, Assistant Director for State & Licensing Relations, OSP

FROM: R. L. Tedesco, Assistant Director for Licensing, DL

SUBJECT: Input to Waterford 3 SSER

The Waterford 3 SSER is scheduled to be published on September 18; however, there appear to be ten issues that could be closed out if SSER publication is delayed three weeks. These issues are identified on the attached list as open item numbers: 5, 8, 10, 11, 14(a), 15, 16, 17, 24(e), and 25. The information needed to close out these issues is currently in-house. It is particularly important that financial qualifications be addressed in the first supplement because the hearing date is tied to the issuance of the supplement which contains the financial evaluation.

I would appreciate your cooperation in providing SSER input to DL by September 22, 1981.

Original signed by:  
 Robert L. Tedesco, Assistant Director  
 for Licensing  
 Division of Licensing

DISTRIBUTION:  
 Docket File 50-382  
 LPDR  
 PDR  
 NSIC  
 TEKA  
 LB#3 Files

RLTedesco  
 FJMiraglia  
 SBlack

8109290047 810917  
 PDR ADOCK 05000382  
 A PDR

OFFICE	DL:LB#3	DL:LB#3	DL:AB/L			
SURNAME	SCBlack:jb	FJMiraglia	RLTedesco			
DATE	9/3/81	9/3/81	9/14/81			

WATERFORD 3  
STATUS REPORT

OPEN ITEMS IN SER	<u>APPL. RESPONSE DATE</u>	<u>STAFF INPUT TO DL</u>
1. Fire Protection	09/18/81	
2. Licensee Qual.	11/30/81	12/31/81
3. PSI/ISI	11/15/81	12/31/81
4. Appendices G&H		closed
5. Emergency Planning	06/17/81	09/15/81
6. Environmental Qual.	10/01/81	
7. Seismic Qual.	in-house	
8. Steam Voiding in R.V.	in-house	09/15/81
9. Feedwater line break analysis	09/10/81	
10. Loss of AC or RCP's during MSLB	in-house	09/15/81
11. Clarification of transient analyses	in-house	09/15/81
12. RCP Shaft Break	10/81	
13. Pressure transient in Shield Bldg.		
14. Thermal-hydraulic design		closed
(a) DNBR	in-house	09/15/81
(b) CPC Software	03/82	
(c) future cycles	09/15/81	
15. Site hazards	in-house	09/08/81
16. Cold Shutdown without leaving CR	in-house	09/15/81
17. Q-List	in-house	09/15/81
18. Turbine missiles	10/30	11/81
19. Emergency Feedwater control		closed
20. IEB 80-06		closed
21. Single failure of control system		closed
22. Organic Materials		closed
23. Plant Procedures	12/01/81	12/31
24. TMI (7)		
(a) I.A.1	12/01/81	
(b) I.B.1.2	12/01/81	
(c) I.C.'s	long term requirement	short term /closed
(d) I.D.1	04/82	05/82
(e) II.E.4.2	in-house	09/15/81
(f) II.F.2	N/S	
(g) II.D.3		closed
25. Financial Qualifications	08/31/81	09/15/81