400 Chestnut Street Tower II

September 22, 1981

SQRD-50-338/81-05

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303



Dear Mr. O'Reilly:

B109300322 B1092 PDR ADDCK 050003

SEQUOYAH NUCLEAR FLANT UNIT 2 - RETRIEVABLE INFORMATION FROM VALVE TAG NUMBERS - SQRD-50-328/81-05 - FIFTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector M. Thomas on December 12, 1980, in accordance with 10 CFR 50.55(e) as NCR SQN CEB 8035. Interim reports were submitted on January 12, March 2, April 2, and June 11, 1981. TVA is proceeding with the development of a cross-reference list on manufacturers' valve drawings versus valve tag numbers. This deficiency involves only the ease of information retrieval from appropriate documentation systems and will not affect power operation at Sequoyah. Scheduled completion of this list is September 30, 1982. We expect to submit our next report by April 7, 1982.

If you have any questions, please call Dave Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Mills, Manager Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

IE27 5.10