

B. Ralph Sylvia
Senior Vice President

Detroit
Edison

6400 North Dixie Highway
Newport, Michigan 48166
(313) 586-4150

March 13, 1990
NRC-90-0045

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Reference: (1) Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43

(2) Title 10, Code of Federal Regulations,
Part 50.55 (a)

Subject: Summary Report of the 1989 Inservice Inspection

Enclosed is the Summary Report of the 1989 Inservice Inspection (ISI) activities performed at Detroit Edison Company's Fermi 2 Nuclear Power Plant. This report represents a summary of the ISI activities from commercial operation (January 23, 1988) through the first scheduled refueling outage.

This report is being submitted in accordance with ASME Section XI, 1980 Edition through Winter 1981 Addenda, paragraph IWA-6230.

If there are any questions, please contact Mr. Bruce Sheffel, ISI Program Manager, at (313) 586-1848.

Sincerely,

B. Ralph Sylvia

cc: A. B. Davis
R. W. DeFayette
W. G. Rogers
J. F. Stang
Region III

*Cont No
R090537929
A047
11*