Troxler Electronic Laboratories 617239 03039217 32-35585-01

Mr. Barnes,

This refers to your request for a new license dated November 25, 2019. In order to continue our review of your request, the following additional information is needed:

- 1. Due to the NRC formatting of the license, we will need the maximum source activity and total activity for each sealed source you are requesting on your license.
- 2. Please provide either of the following:
 - a. A statement that: "Before using licensed material, authorized users will receive the training described in Appendix D of NUREG-1556, Volume 18, Revision 1, 'Consolidated Guidance About Materials Licenses: Program-Specific Guidance About Service Providers'" or
 - b. A description of the training and experience for proposed authorized users.
- 3. Please provide copies of your operating and emergency procedures for our review.
- 4. Please explain if you will be using extremity dosimetry during removal and installation of sealed sources and if not, please provide calculations that monitoring of extremity doses is not required.
- 5. Are there leak check requirements that must be met prior to disconnecting of sealed sources and survey requirements prior to re-installing the sealed sources?

Your reply must be an originally signed and dated letter. The letter may be scanned and submitted as a pdf document attached to an email; or it may be transmitted by facsimile to (610) 337-5269; or it may be sent by regular mail. If we do not receive a reply from you within 30 calendar days from the date of this e-mail, we will assume that you do not wish to pursue your application.

Leo Wardrobe

Health Physicist Nuclear Regulatory Commission, Region I Division of Nuclear Materials Safety, Commercial, Industrial, R&D, and Academic Branch 2100 Renaissance Boulevard, Suite 100 King of Prussia, PA 19406-2713 Office: 610-337-5171 Fax: 610-337-5269

leonardo.wardrobe@nrc.gov

http://www.nrc.gov/