Telephone (412) 456-6000



Nuclear Division P.O. Box 4 Shippingport, PA 15077-0004

> April 25, 1983 ND1SS1:808

Beaver Valley Power Station, Unit No. 1 Docket No. 50-334, License No. DPR-66 LER 82-052/03X-1

J. M. Allen, Acting Regional Administrator United States Nuclear Regulatory Commission Region 1 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Sir:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Updated Licensee Event Report is submitted to further clarify the Cause Description and Corrective Actions previously reported.

LER 82-052/03X-1, Technical Specification 3.7.14.4, Fire Hose Stations.

Very truly yours. S. Wm . Lacey Superintendent

5622

Attachment

Mr. R. C. Haynes April 25, 1983 NDISS1:808 Page 2

*

. *

cc: Director Of Management & Program Analysis United States Nuclear Regulatory Commission Washington, D. C. 20555

J. Hultz, Ohio Edison

Director, Office of Inspection and Enforcement Headquarters United States Nuclear Regulatory Commission Washington, D. C. 20555

Mr. Peter Tam, BVPS Licensing Project Manager United States Nuclear Regulatory Commission Washington, D. C. 20555

W. M. Troskoski, Nuclear Regulatory Commission, BVPS Site Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator, Toledo Edison

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Arthur Alford, Stone & Webster/Boston