

June 17, 1983

Docket No. 50-254
Docket No. 50-265

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

Thank you for your letter dated May 9, 1983, informing us of the steps you have taken to correct the noncompliance which we brought to your attention in Inspection Report No. 50-254/82-26; 50-265/82-26 forwarded by our letter dated April 11, 1983.

As a result of a telephone conversation on May 31, 1983, between Mr. R. Rybak of your staff and Mr. M. Jordan of this office, we understand that Instrument Department procedures have been upgraded to preclude the manipulation of safety related instrument rack stop valves without Operations Department involvement.

We will examine these matters during a subsequent inspection.

Your cooperation with us is appreciated.

Sincerely,

R. L. Spessard
James G. Keppler for
Regional Administrator

cc: D. L. Farrar, Director of
Nuclear Licensing
N. Kalivianakis, Plant
Superintendent

cc w/itr dtd 5/9/83:
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Philip L. Willman, Esq.,
Assistant Attorney General
Environmental Control Division

8306220028 830617
PDR ADOCK 05000254
G PDR

IEO1
11

OFFICE	<i>R III</i>	<i>R III</i>	<i>R III</i>	<i>R III</i>	<i>R III</i>	<i>R III</i>	<i>R III</i>
SURNAME	<i>Probe/rl</i>	<i>Walker</i>	<i>Shafer</i>	<i>Norelius</i>	<i>Schultz</i>	<i>Davis</i>	<i>Keppler</i>
DATE	<i>6/14/83</i>			<i>6/14/83</i>	<i>6-16-83</i>	<i>6/16</i>	<i>6/16</i>