## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T    0   1
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  [0 ] 2   During management review of Instrument Surveillance Procedure F-ISP-66-1 "Scram"
Discharge Volume High Level Instrument Calibration", it was found the Rod Block
[0]4   calibration section had not been performed within 7 days of the planned reactor
[0]5   shutdown on 6/3/83 as required by Technical Specifications Table 4.2.3 (Note 2).
[0]6 The event did not represent a significant hazard to the public health and safety.
0 7
08
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
SEQUENTIAL   OCCURRENCE   REPORT   NO.
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER  X 18 G 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 9 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
Inadequate management controls to implement the Technical Specifications was the
cause. Corrective actionimmediately performed the required surveillance
[1]2 [(calibration was satisfactory). Long term action was to prepare a revision to
procedure F-OP-65 "Startup and Shutdown Procedure" providing a checkoff sheet for
1 4   shutdown prerequisites.
PACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 H 28 0 10 12 13 MA 44 45 46 Management Observation 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA  LOCATION OF RELEASE 36 NA
PERSONNEL EXPOSURES  NUMBER  TYPE  DESCRIPTION 39  NA  11 12 13
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 PDR ADOCK 05000333
1 9 Z 42 NA S PDR 80
PUBLICITY ISSUED DESCRIPTION 45 NA NA NA
7 8 9 10 68 69 80 5 NAME OF PREPARER Hartford N. Keith PHONE: 315-342-3840 Ext. 230 0

## POWER AUTHORITY OF THE STATE OF NEW YORK

JAMES A. FITZPATRICK NUCLEAR POWER PLANT



CORBIN A. McNE<sup>1</sup>LL, JR. Resident Manager P.O. BOX 41 Lycoming, New York 13093

315-342-3840

June 16, 1983 SERIAL: JAFP-83-0631

James M. Allan, Acting Regional Administrator United States Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, Pa. 19406

REFERENCE: DOCKET NO. 50-333 Licensee Event Report: 83-021

Dear Mr. Allan:

We have enclosed the referenced Licensee Event Report in accordance with Section 6.0 of Technical Specifications and USNRC Regulatory Guide 1.16.

If there are any questions concerning this report, please contact Mr. Hartford N. Keith at (315) 342-3840, Extension 230.

Very truly yours,

CORBIN A. McNEILL, JR.

RESIDENT MANAGER

CAM/HNK/cm Enclosure

CC: USNRC Document Control Desk (1)
Asst. Director of Operating Reactors,
USNRC Directorate of Licensing (1)
INPO Records Center, Atlanta, Georgia (1)
Internal Power Authority Distribution
NRC Resident Inspector
Document Control Center
LER/OR File

5 11