


POWER & LIGHT / PO BOX 6008 . NEW ORLEANS. LOUISIANA 70174 . (504) 366-2345

June 29, 1983

W3183-0218 Q-3-A35.07.33

Mr. John T. Collins, Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3 Docket No. 50-382 Significant Construction Deficiency No. 33 "Chilled Water Piping Supports" Seventh Interim Report



REFERENCE: LP&L letter W3I83-0163 dated May 11, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 30, 1983.

At the present time, all corrective action is complete. DCN-MP-459 has been signed off by the contractor as complete along with supporting documentation. This documentation is currently under review by LP&L and Ebasco. This review is expected to be complete by early July, 1983.

A Final Report will be submitted to the USNRC by July 29, 1983.

Very truly yours,

F. J. Drummond Project Support Manager - Nuclear

FJD/RWP/MAL:keh

120202 83062

ADOCK

- cc: 1) Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555
- 3) Mr. E. L. Blake

4) Mr. W. M. Stevenson

10 IE-27

Director
 Office of Management
 Information and Program Control
 U. S. Nuclear Regulatory Commission
 Washington, D. C. 20555