
Hypothetical Conditions at TMI-2 Assuming Early Block Valve Closure

(1)



- Pressurizer level high.
- Reactor coolant pumps tripped (NPSH) just after this time.
- System depressurizing.