APR 2 4 1991

DOD

TEOP

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President Nuclear-Davis-Besse Centerior Service Company c/o Toledo Edison Company 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Mr. A. G. Januska and Ms. B. L. Hamrick of this office on April 1 - 5, 1991, of activities at the Davis-Besse Nuclear Power Station, Units 1 authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. R. Scott and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. In addition, our Mobile Laboratory was at the site during the inspection to perform independent measurements of radioactivity.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely.

"Driginal signed by V. L. Axelson"

L. Robert Greger, Chief Reactor Programs Branch


Enclosure: Inspection Report No. 50-346/91007(DRSS)

PDR

RIII

Hamrick

See Attached Distribution



9105020161 910424 PDR ADOCK 05000346

Schumacher Jack



Toledo Edison Company

Distribution

cc w/enclosure: L. Storz, Plant Manager DCD/DCB (RIDS) OC/LFDCB Resident Inspector, RIII James W. Harris, State of Ohio Robert E. Owen, Ohio Department of Health A. Grandjean, State of Ohio, Public Utilities Commission

1.