June 7, 1991

Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Attn: Document Control Desk

Subject: Quad Cities Station Units 1 and 2

Status of NRC Bulletin 88-10 NRC Docket Nos. 50-254/265

References:

(a) NRC Bulletin 88-10, dated November 22, 1988.

- (b) M. Richter (CECo) letter to U.S. NRC, dated September 13, 1989.
- (c) M. Richter (CECo) letter to U.S. NRC, dated November 9, 1989.
- (d) D. Taylor (CECo) letter to U.S. NRC, dated November 29, 1990.

Dear Sir:

NRC Bulletin 88-10, Reference (a), requested that actions be taken to provide reasonable assurance that molded-case circuit breakers (MCCB) purchased for use in safety-related applications without verifiable traceability to the circuit breaker manufacturer (CBM) perform their safety function. In Reference (b), Commonwealth Edison Company (CECo) reported that both units at Quad Cities Station had non-traceable MCCBs installed in safety-related applications, and that these breakers would be replaced (by traceable breakers) to complete Bulletin Action 5. CECo indicated in reference (b) that breaker replacement would be completed by the end of the second refueling outage beginning after March 1, 1989 for each unit at Quad Cities Station. These refueling outages were scheduled for November 1990 for Quad Cities Unit 1 and December 1991 for Quad Cities Unit 2. References (c) and (d) provided the staff with periodic updates of the status of MCCB replacement at Quad Cities Station.

This letter provides notice that non-traceable safety-related MCCB replacement has been completed at Quad Cities Station in advance of the schedule committed to in Reference (b). The traceable replacement breakers for Units 1 and 2 were procured safety-related, and meet the criteria of Bulletin Action 7.

U.S. Nuclear Regulatory Commission

June 7, 1991

This letter therefore, completes the reporting requirements and notifies the staff of the completion of all action items associated with NRC Bulletin 88-10 for Quad Cities Station Units 1 and 2.

Please direct any questions that you may have concerning this response to this office.

Respectfully,

Jujn

D.L. Taylor Generic Issues Administrator

DT/reg 608/38 & 39

cc: A.B. Davis - Regional Administrator, Region III Senior Resident Inspector - Quad Cities Station L. Olshan - NRR Project Manager