



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

*Washington PDK
50-338*

OCT 23 1978

In Reply Refer To:
RII:EHW
50-338/78-25

Q

Virginia Electric and Power Company
ATTN: Mr. W. L. Proffitt
Senior Vice President, Power
P. O. Box 26666
Richmond, Virginia 23261

Gentlemen:

This refers to the inspection conducted by E. H. Webster of this office on August 21-25, 1978, of activities authorized by NRC License No. NPF-4 for the North Anna Unit No. 1 facility, and to the discussion of our findings held with J. A. Ahladas at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.


781206

OCT 23 1978

Virginia Electric and Power Company -7-

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,



F. J. Long, Chief
Reactor Operations and Nuclear
Support Branch

Enclosure:
Inspection Report No. 50-338/78-25

cc:
Mr. J. A. Ahladas, Station Manager
North Anna Power Station
Box 402
Mineral, Virginia 23117

Mr. S. V. Lowry
Senior Resident Engineer
P. O. Box 38
Mineral, Virginia 23117