



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

August 18, 1982

Mr. James G. Keppler, Regional Administrator
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Braidwood Station Units 1 and 2
I&E Inspection Report Nos.
50-456/81-14 and 50-457/81-14

- Reference (a): January 5, 1982, letter from
C. E. Norelius to Cordell Reed.
- (b): February 4, 1982, letter from
L. O. DelGeorge to J. G. Keppler.


Dear Mr. Keppler:

This is to provide information regarding liftoff test of tendons stressed at Braidwood using gauges which were later found to be out of tolerance. This matter was discussed in the inspection report attached to reference (a) and was the subject of a Notice of Violation.

In responding to the Notice of Violation we indicated that a liftoff test would be performed on the last tendon stressed on each day the gauges were found to be out of tolerance. The results of these tests would be evaluated by the architect-engineer to determine if further action is necessary. We expected to be able to supply a report of this evaluation by June 30, 1982. It now appears that the testing will be done in October of 1982 and that our final report will be available by December 31, 1982.

Please address questions regarding this matter to this office.

Very truly yours,


T. R. Tramm
Nuclear Licensing Administrator

lm

4775N
8209160604 820913
PDR ADOCK 05000456
Q PDR

AUG 24 1982

1E01