10 CFR 2.201	SAFETY INSPECTION	U.S. NUCLEAR REGULATORY COMMISSION DM B - 15- 9 - 12 Capy CORRECTED COPY
1. LICENSEE	2 REGIONAL	OFFICE
HAMMOND CLINIC 7905 CALUMET AV MUNSTER, INDIAN	ENUE	ION III
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION
000-11477	13-16680-01	10-20-82
X 3. During this inspection certain of THIS IS A NOTICE OF VIOLAT		
of a		
of a B. Containers located in		. 10 CFR 20.203(b), (c), (d), (e) or 34.42. were not properly
of a B. Containers located in	ce of radioactive material. 10 CFR 20.203(f)(1), or (f)(2	. 10 CFR 20.203(b), (c), (d), (e) or 34.42. were not properly
B. Containers located in labeled to indicate the present	ce of radioactive material. 10 CFR 20.203(f)(1), or (f)(2	. 10 CFR 20.203(b), (c), (d), (e) or 34.42. were not properly 2), of sealed sources were not performed at the proper
B. Containers located in labeled to indicate the present frequencies. 10 CFR D. Records of LEAK TEST 10 CFR	ce of radioactive material. 10 CFR 20.203(f)(1), or (f)(2)	were not properly of sealed sources were not performed at the proper cense Condition Number (2) were not properly maintained.
of a B. Containers located in	REQUIRED BY 10 CFR 35.14 (E) or License Condition posted or otherwise made available. 10 CFR 19.11.	were not properly of sealed sources were not performed at the proper cense Condition Number (2) were not properly maintained.
B. Containers located in	ce of radioactive material. 10 CFR 20.203(f)(1), or (f)(2) Li REQUIRED BY 10 CFR 35.14 (E) or License Condition	were not properly of sealed sources were not performed at the proper cense Condition Number (2) were not properly maintained. tion Number were not made in accordance

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by

the NRC.

8210280140 821020 NMS LIC30 13-16680-01 PDF

PDR