

APPENDIX A
NOTICE OF VIOLATION

Washington Public Power Supply System
3000 George Washington Way
Richland, Washington 99352

Docket No. 030-13720
License No. 46-17964-01


As a result of the inspection conducted on August 31 - September 3, 1982, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C) 47 FR 9987 (March 9, 1982), the following violation was identified. This item described below, involving possession of licensed material not specifically authorized, is classified as a Severity Level IV violation after careful consideration of the factors involved in this specific instance.

10 CFR 30.3 states in part that; "Except for persons exempt as provided in this part and Part 150 of this chapter, no person shall... receive, acquire, own, possess or use, byproduct material except as authorized in a specific or general license issued pursuant to the regulation in this chapter."

Contrary to this requirement on August 31, 1982 Washington Public Power Supply System employees received at Warehouse 4 a three curie Americium-241/Beryllium neutron source (AMN 23) not authorized in their specific License No. 46-17964-01 and no exemption applied.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, the Washington Public Power Supply System is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.



F. A. Wenslawski, Chief
Reactor Radiation Protection Section

dated OCT 12 1982