



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

November 17, 1982

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Failure of a Hot Leg Loop B Sample Isolation Valve

The License Event Report for this occurrence is attached to this letter.

This event is reported in compliance with Technical Specification 6.7.B.2.(b) since it placed the plant in a degraded mode as permitted by limiting conditions of operations.

for Simon Fehn

David Musolf
Manager - Nuclear Support Services

DMM/SAF/js

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman