Docket No. 99900733/82-01

American Warming and Ventilating, Inc. ATTN: Mr. W. B. Ball, Jr. President 1310 Indian Wood Circle Maumee, Ohio 43537

Gentlemen:

Thank you for your letter of August 2, 1982, in response to our letter dated July 1, 1982. This is to advise you that the tag number for the damper that was observed to be sealed with the improper sealant was: IP9438A1. We have no further questions at this time and will review your corrective actions and preventive measures during a future inspection.

U. POTAPO/S"
Uldis Potapovs, Chief
Vendor Program Branch

Sincerely,

bcc: NRC:PDR JTCollins EHJohnson RLBangart JAMarshall WEFoster

RIV CI:R&CPS&V WEFoster/rcv

SC: R&CPS W/ IBarnes 11//7/82

BC: VPBCP UPotapovs 11/7/82 D: V&TP RLBangart 11/ /82 D:ES THE EHJohnson 11/19/82

74.01

rh