

SAFETY INSPECTION

1. LICENSEE

Medical X-Ray Center
Department of Radiology
1417 South Minnesota Ave
Sioux Falls, SD 57105

2. REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

3. DOCKET NUMBER(S)

30-1915

4. LICENSE NUMBER(S)

40-01493-03

5. DATE OF INSPECTION

11/5-16/82

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.
THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.
- ☐ A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b), (c), (d), (e) or 34.42.
- ☐ B. Containers located in _____ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).
- ☐ C. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ License Condition Number _____.
- ☒ D. Records of leak tests after July 30, 1971 for Th-230 source were not properly maintained. 10 CFR _____ or License Condition Number 14A.
- ☐ E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
- ☐ F. Reports or notifications of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
- ☐ H. _____
- ☐ I. _____
- ☐ J. _____
- ☐ K. 8212030007 821116
NMS LIC30
40-01493-03 PDR

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

NRC FORM 755-A (11-87) (E MC 053)	DOCKET NO. (8 digits) OR LICENSE NO. (BY PRODUCT) (13 digits)		REPORT NO. SEQ.		MODULE NUMBER	
	03019115		NO. SEQ.		57872018 VI	
	03019115		A B C D		VIOLATION SEVERITY OR DEVIATION 1 2 3 4 5 6 27	

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

1. License Condition 14.A requires, in part, that records of leak tests ~~to~~ shall be maintained for inspection by the Commission.

Contrary to this requirement, Records of leak tests purportedly performed during the period July 30, 1981 to November 16, 1982 were not available on the day of inspection.