

U.S. NUCLEAR REGULATORY COMMISSION
REGION I

Report No. 50-387/82-23

Docket No. 50-387 License No. NPF-14 Safeguards Group IV

Licensee: Susquehanna Power and Light Company
Two North Ninth Street
Allentown, Pennsylvania 18101

Facility Name: Susquehanna Steam Electric Station

Inspection At: Berwick, Pennsylvania

Inspection Conducted: August 16, 1982

Date of Last Physical Security Inspection: July 12-16, 1982

Type of Inspection: Announced Preoperational Physical Protection Inspection

Inspectors: for Robert J. Bailey 11/19/82
W. J. Madden, Physical Protection Inspector date signed

for Robert J. Bailey 11/19/82
J. M. Dunlap, Physical Protection Inspector date signed

Approved By: for James H. Joyner 11/19/82
A. J. Gody, Chief, Safeguards and Fuel date signed
Facilities Section, Nuclear Materials and
Safeguards Branch

Inspection Summary: Inspection on August 16, 1982 (Report No. 50-387/82-23)
Areas Inspected: Review of Licensee Actions relative to excessive alarms.
The inspection involved 8 inspector-hours onsite by two Region I inspectors and was begun during regular hours.

Results: The licensee was in compliance with NRC requirements in the areas examined during this inspection.

DETAILS

1. Key Persons Contacted

- *H. W. Keiser, Plant Superintendent
- *F. T. Eisenhuth, Senior Compliance Engineer
- *K. Hart, Site Technical Advisor
- *R. L. Stotler, Supervisor of Security
- *C. D. Lopes, Senior Security Shift Supervisor
- *R. E. Gaudreau, Security System Coordinator
- *G. G. Rhoads, NRC Resident Inspector
- *J. F. McCann, NRC Resident Inspector

*denotes those present at the exit interview.

2. 30703 - Exit Interview

The scope and findings of the inspection were discussed with the licensee representatives (denoted in paragraph 1) at the conclusion of the inspection on August 16, 1982.

3. 92713 - Independent Inspection Effort for Safeguards Inspections

(SGI)