Attachment to AECM-83/027

|                     | Page 1 of 1  |
|---------------------|--|
|                     | CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)   |
| 0 1                 | M S G G S 1 2 0 0 - 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5 5 5 1 6 15 CAT 58  |
| CON'T<br>0 1<br>7 8 | REPORT L 6 0 5 0 0 0 4 1 6 7 0 7 0 9 8 2 8 0 1 1 3 8 3 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  On December 15, 1982, a QA audit identified that a requirement of T.S.4.7.8 had not  |
| 0 3                 | been met on several dates. T.S.4.7.8 requires that temperatures in selected areas to   |
| 0 4                 | be determined at least once per 12 hours. This was not done on the following 1982  |
| 0 5                 | dates: 7/9-14, 16, 18-31; 8/1-5, 9-14, 16, 22-29; 9/1-10, 16, 25; and 10/8. This had   |
| 0 6                 | no effect on the health and safety of the public and did not constitute a threat to  |
| 0 7                 | plant safety. A similar event was reported as LER 82-006/01 T-0.   |
| 0 8                 | 9 SYSTEM CAUSE CAUSE COMP. VALVE   |
| 0 9 8               | SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC |
|                     | 17 REPORT   8   2   1   1   7   3   27   28   29   30   31   32   30   32   30   31   32   30   31   32   30   30   31   32   30   30   30   30   30   30   30   |
| 1 0                 | Operating personnel had placed "NA" on some of the data sheets on the daily log due  |
| 111                 | to unfamiliarity with the revised procedure. A review of entries made subsequent to  |
| 1 2                 | the event dates indicates procedural and T.S.4.7.8 compliance. No further action is  |
| 13                  | required. This is being submitted as a final report.   |
| 1 4                 | 80   |
| 1 5                 | FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA Audit 45 46 80  |
|                     | ACTIVITY CONTENT SELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY 35 NA  LOCATION OF RELEASE 36 NA  80  |
| 1 7                 | NUMBER TYPE DESCRIPTION (39) NA 9 11 12 13 PERSONNEL INJURIES 13   |
| n n                 | NUMBER DESCRIPTION (41) NA   |
| 7 8                 | 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION  |
| 7 8                 | NA 8301200245 820112   |
| 20                  | PUBLICITY ISSUED DESCRIPTION 45 S ADOCK 05000461 PDR 68 69 80 5  |
|                     | NAME OF PREPARER Original signed by Ron Byrd PHONE   |