



Northern States Power Company

414 Nicollet Mall Minneapolis, Minnesota 55401 Telephone (612) 330-5500

January 12, 1983

Regional Administrator Region III U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT Docket No. 50-282 License No. DPR-42

Leak In Piping Containing 12% Boric Acid Solution

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.1.(i) due to the potentially generic nature of the event.

Limon Febru for David Musolf

Manager - Nuclear Support Services

DMM/SAF/bd

cc: NRC Document Control Desk (1)

NRC Resident Inspector

MPCA

Attn: J W Ferman

Attachment

IE 22