Bulletin Reply 82-04

Docket No. 50-312



SACRAMENTO MUNICIPAL UTILITY DISTRICT 

6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

January 17, 1983

R H ENGELKEN REGIONAL ADMINISTRATOR REGION V OFFICE OF INSPECTION & ENFORCEMENT U S NUCLEAR REGULATORY COMMISSION 1450 MARIA LANE SUITE 210 WALNUT CREEK CA 94596

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION UNIT NO. 1 IE BULLETIN NO. 82-04: DEFICIENCIES IN PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES

The subject bulletin identified deficiencies associated with containment electrical penetration assemblies manufactured by the Bunker Ramo Company. The District has purchased and installed only containment electrical penetration assemblies manufactured by the Conax Corporation. Therefore, no further action is required.

John J. Mattimoe General Manager

John of matternoe