

John C. Brons Executive Vice President Nuclear Generation

September 26, 1990 JPN-90-065

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Stop P1-137 Washington, D.C. 20555

SUBJECT:

James A. FitzPatrick Nuclear Power Plant

Docket No. 50-333

NRC BULLETIN 90-01, ROSE YOUNT TRANSMITTERS

References:

NYPA letter, W. Fernandez to NRC, dated

July 19, 1990, "Response to NRC Bulletin 90-01,"

(JAFP-90-0549).

2. NRC Bulletin 90-01, "Loss of Fill-oil in Transmitters

Manufactured by Rosemount."

Dear Sir:

In Attachment 1 of Reference 1, the Authority submitted a list of suspect Rosemount transmitters as requested by the NRC staff in NRC Bulletin 90-01 (Reference 2). During a discussion of our response with the NRC staff, the Authority noticed a typographical error in that list. Transmitter 16PT-101B in the "Instrument" column should be 10PT-101C. The other information relating to this instrument is correct.

If you have any questions regarding this matter, please contact Mr. J. B. Ellmers.

Very truly yours,

John C. Brons
Executive Vice President
Nuclear Generation

CC:

See next page

cc: Office of the Resident Inspector
U. S. Nuclear Regulatory Commission
Post Office Box 136
Lycoming, New York 13093

Regional Administrator U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19400

David E. LaBarge
Project Directorate I-1
Division of Reactor Projects I/II
U. S. Nuclear Regulatory Commission
Mail Stop 14 B2
Washington, D. C. 20555