



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

February 25, 1986

Inv.

The Honorable Edward Markey, Chairman
Subcommittee on Energy Conservation and Power
Committee on Energy and Commerce
United States House of Representatives
Washington, D.C. 20515


Dear Mr. Chairman:

Following the loss of integrated control system power and overcooling transient that occurred on December 26, 1985 at the Rancho Seco Nuclear Generating Station, operated by the Sacramento Municipal Utility District (SMUD), the NRC established a special Incident Investigation Team (IIT) to investigate the incident.

For your information, I am enclosing an advance copy of the Team report which documents the circumstances and probable causes of the incident. The report discusses the major implications of the event and includes the Team's findings and conclusions.

The report will be made available to the public this morning when the Commission is briefed by the IIT. I will forward to you a copy of the published report, NUREG-1195, when it is available from the printer.

Sincerely,


Carlton Kammerer, Director
Office of Congressional Affairs

Enclosure:
As stated

cc: Rep. Carlos Moorhead

IDENTICAL LETTER SENT TO:
Sen. Simpson/cc: Sen. Hart
Rep. Udall/cc: Rep. Lujan
Sen. Wilson
Sen. Cranston
Rep. Fazio
Rep. Shumway

9101300243 901011
PDR FOIA
POTTER90-391 PDR

A/49