

## HURON MEMORIAL HOSPITAL

Telephone (517) 269-9521

1100 South Van Dyke Road  
BAD AXE, MICHIGAN 48413

United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

January 14, 1991

*Licence File**21-17093-01*

Re: Nuclear Regulatory Commission Inspection December 12, 1990

Gentlemen:

This letter is in reply to the inspection that was conducted at Huron Memorial Hospital on December 12, 1990 by inspector B.A. Parker from your office of Region III. As a result of the inspection of this date, December 12, 1990, we were found to be in non compliance with the following items of 10 CFR part II appendix C; the general statement of policy and procedure for NRC enforcement actions of 1985. Item # 10 CFR 35.22 (a) part II requires the Radiation committee to meet at least quarterly.

This item of non compliance was addressed in January 1990 at our Radiation Safety Committee by the physicist. It was the recommendation of the committee to meet quarterly when the physicist was at our facility. Since January 1990, the Radiation Safety Committee has met quarterly.

Item # 2

To be in compliance with testing of new equipment, i.e dose calibrators, a policy has been instituted effective January 1, 1991 requiring any new or used dose calibrators to be properly calibrated before usage.

In summation, the two non compliance items i.e. Radiation Safety Committee meetings and dose calibrator calibration have both had policies instituted to prevent further non compliance.

If you would like further information, feel free to write to Huron Memorial Hospital, 1100 South Van Dyke, Bad Axe, Michigan 48413.

Sincerely,

*James B. Gardner*  
James B. Gardner CEO

JG/js

cc: Richard Beaver CNMT  
David L. Carter M.D.

9102040271 910114  
REG3 LIC30  
21-17093-01 PDR

JAN 22 1991 110  
**IE 07**