GULF STATES UTILITIES COMPAN RIVER HEND STATION POST OFFICE BOX 720 ST FRANCISVILLE LOLISIANA 70775 ANEA CODE 504 835-8094 346-8651 March 6, 1990 RBG- 34,574 File No. G9.5, 224.600 U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555 Gentlemen: River Bend Station - Unit 1 Docket No. 50-458 Enclosed please find Gulf States Utilities Company's Inservice Inspection Summary Report for the River Bend Station inservice inspection performed during the third refueling outage pursuant to 10CFR50.55a. This report is submitted for your information in accordance with ASME Boiler and Pressure Vessel Code, Section XI-Division I, Subsubarticle IWA-6230, 1980 Edition with Addenda through Winter 1981. Sincerely, Odell Manager-Oversight River Bend Nuclear Group Was a stomb WHO/LAE/LID/MSF Enclosure U. S. Nucl ar Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76011 NRC Resident Inspector P. O. Box 1051 St. Francisville, LA 70775 Claudia Abbate 11555 Rockville Pike Rockville, MD 20852 9103150001 910306 PDR ADOCK 05000458 140001