

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 NY IPS 2 00 - 000000 - 00 41 11 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CON'T

01 REPORT SOURCE X 05000247 081878 082878 9
60 61 DOCKET NUMBER 69 70 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Teledyne Isotopes, our contracting laboratory, provided Con Edison
03 with a confirmatory telephone report on 8/18/78 that the activity
04 of our Hudson River aquatic vegetation sample taken from Lovett on
05 June 29, 1978 exceeded 10 times the historical level at this location.
06 This event does not have any significant environmental consequence,
07 since it was determined that the sample was inadvertently contaminated
08 after collection and that the activity present was not due to plant
09 operations.

09 X X 11 C 12 Z 13 Z Z Z Z Z 14 Z 15 Z 16
9 10 11 12 13 14 15 16 17 18 19 20
17 LER REPORT NUMBER 78 21 22 23 24 25 26 27 28 29 30 31 32
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
Z 18 X 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 21

10 The cause of the anomalous sample activity is considered to be
11 inadvertent contamination of the sample sometime after collection
12 but before analysis. Sample container split open spilling the
13 contents and allowing samples to get contaminated. In the future
14 more durable containers will be used.

15 FACILITY STATUS 28 1 0 0 29 N.A. 30 Notification by Environmental Lab.
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
16 RELEASED OF RELEASE 23 Z 34 N.A. 35 N.A. 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
17 PERSONNEL EXPOSURES 38 0 0 0 1 Z 39 N.A.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
18 PERSONNEL INJURIES 40 0 0 0 41 N.A.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
19 LOSS OF OR DAMAGE TO FACILITY 42 Z 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
20 RELEASES 44 N 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Dupe 7809060013

Steve Masciulli

(212) 460-3384

09/01/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-008/247/286

REC: GRIER B H
NRC

ORG: CAHILL W J
CONSUL EDISON OF NY

DOCDATE: 08/28/7
DATE RCVD: 09/01/

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-247/78-023) ON 08/18/78 CONCERNING
ACTIVITY OF APPLICANT'S HUDSON RIVER AQUATIC VEGETATION SAMPLE TAKEN FROM
LOVETT ON JUNE 29, 1978 EXCEEDED 10 TIMES THE HISTORICAL LEVEL... W/ATT.

PLANT NAME: INDIAN PT - UNIT 1
INDIAN PT - UNIT 2
INDIAN PT - UNIT 3

REVIEWER INITIAL: XJM
DISTRIBUTER INITIAL: DL

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

ENVIRONMENTAL EVENT/ABNORMAL OCCURENCE
(DISTRIBUTION CODE C003)

FOR ACTION: BR CHIEF EPB#1 BC**W/7 ENCL

FOR INFO: D EISENHUT**LTR ONLY(1)
FOR INFO: WAMBACH**LTR ONLY(1)

ORB#1 BC**LTR ONLY(1)
ORB#1 LA**LTR ONLY(1)

INTERNAL: REG FILE**W/ENCL
I & E**W/2 ENCL
HANAUER**W/ENCL
EEB**W/ENCL
ENVIRO SPEC BR**W/ENCL

NRC PDR**W/ENCL
OELD**W/ENCL
MIPC**W/ENCL
L CROCKER**W/ENCL
EFFLUENT TREAT SYS**W/ENCL

EXTERNAL: LPDR'S
WHITE PLAINS, NY**W/ENCL
TIC, LIZ CARTER**W/ENCL
NSIC**W/ENCL
ACRS CAT 3**W/ENCL

DISTRIBUTION: LTR 26 ENCL 22
SIZE: 1P+2P+1P

CONTROL NBR: 782480010

***** THE END *****

ENVIRO -

cap