

EAST TOWNE MEDICAL ASSOCIATES

811 East Wisconsin Avenue  
Milwaukee, Wisconsin 53202  
(414) 276-4616

Burton A. Waisbren, Jr., M.D.  
Garland W. Yarbrough, M.D.  
Allen H. Schaeffer, M.D.

August 21, 1981

**Port Washington Office:**  
1032 South Spring Street  
Port Washington, WI 53074  
(414) 284-5806 or  
931-8664

Mr. D. G. Wiedeman, Acting Chief  
Material Radiation Protection Section 1  
U. S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

**Random Lake Office:**  
712 Random Lake Road  
Random Lake, WI 53075  
(414) 934-4377

Reference: License No. 48-18944-04

Dear Mr. Weideman:

With reference to your letter dated August 4, 1981, regarding the inspection conducted by Mr. R. E. Burgin, we have two radiation survey instruments in the department,

- 1 - Ludlum, Model #14C
- 2 - Lidlum, Model #177 (lab monitor)

We felt that as the Ludlum #177 was on site during the calibration of Model #14C, we would not require a loaner to conduct surveys of low levels of activity that we handle on our premises.

However, to comply with our license application, a loaner survey meter will be obtained from Health Physics Associates, Ltd. when Model #14C is out for repairs or annual calibration.

We hope the above response is satisfactory.

Sincerely,

*Howard H. Johnson M.D.*  
Howard Johnson, M.D.  
Radiation Safety Officer

State of Wisconsin )  
                                  )SS.  
County of Milwaukee)

Subscribed to and sworn before me this  
21st day of August, 1981.

*Lynn B. Laube*  
Notary Public, State of Wisconsin  
My Commission Expires: 11-21-82



0109170253 810904  
NMS LIC30  
48-18944-01 PDR

AUG 25 1981