

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	A	Y	K	R	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	3	9						14	15	25										26	30					57	CAT	58	
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE									

CON'T

0 1 REPORT SOURCE L 0 5 0 0 0 0 2 9 7 0 8 1 1 8 1 8 0 9 1 0 8 1 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While checking the Health Physics surveillance schedule it was determined
0 3 | that the surveillance requirements were not met. T.S. 4.7.6.2 requires
0 4 | sealed sources be tested every 6+25% months. The 6+25% month time limit
0 5 | was missed by 3 days. A similar occurrence was reported as LER 80-03. There
0 6 | were no adverse effects to the public health or safety as a result
0 7 | of this event.

0 8		7 8		9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE		7															
0 8		7 8		9		Z Z (11)		A (12)		D (13)		Z Z Z Z Z (14)						Z (15)		Z (16)																	
7 8		9		10		11		12		13		18						19		20																	
17		LER/RO REPORT NUMBER		EVENT YEAR		21		22		23		SEQUENTIAL REPORT NO.		24		25		OCCURRENCE CODE		26		27		REPORT TYPE		28		29		REVISION NO.		30		31		32	
17		LER/RO REPORT NUMBER		8 1		21		22		23		0 2 3		24		25		0 3		26		27		L		28		29		0		30		31		32	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																					
H (18)		Z (19)		Z (20)		Z (21)		0 0 0 0 (22)		N (23)		N (24)		Z (25)		Z J 9 9 (26)																					
23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The root cause of this event was the failure of responsible personnel to
1 1 | insure the surveillance time limit was met. The surveillance procedure
1 2 | was performed with satisfactory results and the personnel responsible we
1 3 | re reminded of their responsibilities. No further actions are deemed nec
1 4 | essary.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	C	28	0	7	5	29	N/A	B	31	Personnel Observation	32
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
1	6	Z	33	Z	34	N/A	35	N/A	36			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	37	Z	38	N/A	39			
PERSONNEL INJURIES		NUMBER		DESCRIPTION								
1	8	0	0	0	40	N/A	41					
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION								
1	9	Z	42	N/A	43							
PUBLICITY		ISSUED		DESCRIPTION								
2	0	N	44	N/A	45							
NRC USE ONLY												

8109210191 810910
PDR ADCK 05000029
S PDR

PREPARED BY L. D. FRENCH

PHONE: (413) 625-6140

10