DAB/LER



September 16, 1981

L81-952

FILE: RR 2 (NP-33-81-60)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinios 60137

Dear Mr. Keppler:

Reportable Occurrence 81-050

Davis-Besse Nuclear Power Station Unit 1

Date of Occurrence: August 20, 1981

Enclosed are three copies of Licensee Event Report 81-050 with supplemental information sheets which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray

Station Superintendent

Terry D Munay

Davis-Besse "uclear Power Station

TDM/1jk

Enclosure

cc: Mr. Victor Stello, Jr., Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management and Program Analysis Encl: 3 copies

Mr. Luis Reyes NRC Resident Inspector Encl: 1 copy

THE TOLEDO EDISON COMPANY

8109280469 810916 PDR ADDCK 05000346