



**Wisconsin Electric** POWER COMPANY  
 231 W. MICHIGAN, P.O. BOX 2046, MILWAUKEE, WI 53201

September 11, 1981

Mr. J. G. Keppler, Regional Director  
 Office of Inspection and Enforcement,  
 Region III  
 U. S. NUCLEAR REGULATORY COMMISSION  
 799 Roosevelt Road  
 Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

DOCKET NO. 50-266  
LICENSEE EVENT REPORT NO. 81-012/01T-0  
POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report No. 81-012/01T-0 (a 14-day follow-up report) which provides a description of an event reportable according to Technical Specification 15.6.9.2.A.6, "Personnel error or procedural inadequacy which prevents, or could prevent by itself, the fulfillment of the functional requirements of systems required to cope with accidents analyzed in the FFDSAR".

In the 24-hour notification this event was classified as being reportable in accordance with Technical Specification 15.6.9.2.A.5; however, further study of the event has concluded that Technical Specification 15.6.9.2.A.6 is the most accurate section for reporting this occurrence.

Very truly yours,

Executive Vice President

Sol Burstein

Enclosure

Copy to NRC Resident Inspector

IE22  
 S  
 1/1

8109280551 810911  
 PDR 4DOCK 05000266  
 S PDR

SEP 14 1981

2222