U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECTION AND ENFORCEMENT

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

| Consumers Power Company 1945 W. Parnall Road Jackson, Michigan 49201 | | | U.S. Nuclear Regulatory Commission Office of Inspection & Enforcement Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137 | |
|---|---|-----------------------------|--|---|
| 3. 00 | CKET NUMBER(S) | 4. LICENSE NUMBER(| 6) | 8. DATE OF INSPECTION |
| 030-15280 21-086 | | 21-08606- | 09 | 10/08/81 |
| The in | PECTION FINDINGS aspection was an examination of the activities in the second interviews with personnel, and of the records, interviews with personnel, and of the second interviews with personnel. | itions of your license. The | inspection cons | relate to radiation safety and to compliance with the isted of selective examinations of procedures and repress a result of this inspection are as follows: |
| No items of noncompliance or unsafe conditions were found. | | | | |
| The | following items of noncompliance rela | ted to records, signs, a | nd labels were | found: OCT 1 9 1981 |
| | A. Rooms or areas were not properly | posted to indicate the | presence of a | RADIATION AREA 10 CFR 20.203(b) or 34.42 |
| | B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42 | | | |
| | C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d) | | | |
| | D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e) | | | |
| | E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2) | | | |
| | F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b) | | | |
| | G. Form NRC-3 was not properly posted. 10 CFR 20.206(c) | | | |
| | H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b) | | | |
| | Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d) | | | |
| | J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51 | | | |
| | K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c) | | | |
| | L. Records of inventories were not maintained. 10 CFR 34.26 | | | 1/2 |
| | M. Utilization logs were not maintain | ed. 10 CFR 34.27 | | Ann: |
| | N. Records of radiation survey instru | ment calibration were | not maintaine | d. 10 CFR 34.24 DOE BOR BER |
| | O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license. | | | |
| | P. Other | | | |
| | | D.R. | Shop | On. RC Inspector) |
| 7. Th | ne NRC Inspector has explained and | I understand the its | ems of noncon | npliance listed above. The items of |
| noncompliance will be corrected within the next 30 days. 8110200242 811008 NMS LIC30 21-08606-09 PDP | | | | |
| | (Date) | | (1) | Title - B. W. |
| - | (Date) | | (Licensee K | epresentative - Title or Position) |